Property Consultants Linking people to properties



£1,195 PCM Challney Close Luton, Bedfordshire LU4 9TF

*dg Property Consultants * * AVAILABLE TO RENT * A superbly presented, fully refurbished 3 bedroom detached Bungalow, located towards the L&D borders. Accommodation comprises: Entrance hall, large combined lounge/dining room, refitted kitchen/breakfast room, 3 good size bedrooms, refitted modern family bathroom. Benefits include: Gas central heating, double glazing, front & rear gardens, ample off rd parking plus single garage. Available straight away as furnished or unfurnished. Viewing is a must! CALL TEAM dg FOR FURTHER DETAILS AND TO ARRANGE A VIEWING 01582-580500

Detached Bungalow
Superbly Presented Throughout
3 Bedrooms
Combined Lounge/ Diner
Fitted Kitchen/Diner
Double Glazed & Gas C-H
Garage & Off Road Parking
Modern Bathroom
Front & Rear Gardens
Available Straight Away /
Furnished/Unfurnished





Lettings: T: 01582 592700 E: lettings@dgpropertyconsultants.co.uk W: dgpropertyconsultants.co.uk

Ground Floor

Entrance Hall

13'3" x 3'7"

Wooden laminate flooring, double power point(s), access to loft space, smoke detector, storage cupboard, opening kitchen breakfast room, door to lounge/dining room, doors to bedrooms and bathroom.

Left clean, tidy & rubbish free. No visible marks to walls and ceiling as all has been redecorated. The pictures illustrates. Should you require larger pictures then these can be emailed on request.



View of Entrance Hall

Left clean, tidy & rubbish free. No visible marks to walls and ceiling as all has been redecorated. The pictures illustrates. . Should you require larger pictures then these can be emailed on request.



View of Entrance Hall

Left clean, tidy & rubbish free. No visible marks to walls and ceiling as all has been redecorated. The pictures illustrates. . Should you require larger pictures then these can be emailed on request.





Lounge/Dining Room

21'0" x 11'5"

Two replacement uPVC double glazed windows to rear incorporating uPVC double glazed french double doors to rear to garden with curtains, two double radiators, fitted carpet, TV point(s), double power point(s), feature fireplace with electric convector fire with remote control, Furniture: Leather suite. coffee table

Left clean, tidy & rubbish free. No visible marks to walls and ceiling as all has been redecorated. The pictures illustrates. . Should you require larger pictures then these can be emailed on request.

View of Lounge/Dining Room

Left clean, tidy & rubbish free. No visible marks to walls and ceiling as all has been redecorated. The pictures illustrates. . Should you require larger pictures then these can be emailed on request.





View of Lounge/Dining Room

Left clean, tidy & rubbish free. No visible marks to walls and ceiling as all has been redecorated. The pictures illustrates. . Should you require larger pictures then these can be emailed on request.



PROTECTED



Kitchen/Breakfast Room

9'11" x 11'3"

Refitted with a matching range of base and eye level units with worktop space over, 1+1/2 bowl stainless steel sink unit with single drainer and mixer tap with tiled splashbacks, Appliances: Fridge/freezer and automatic washing machine, theses are left for the tenancts to use, but should they break down, then the tenants should replace them with their own appliances, built-in oven, built-in four ring gas hob with extractor hood over, replacement uPVC double glazed window to rear, single radiator, wooden laminate flooring, double power point(s) with fluorescent strip, Upvc double glazed door to rear garden. Furniture: Table & 4 x chairs.

Left clean, tidy & rubbish free. No visible marks to walls and ceiling as all has been redecorated. The pictures illustrates. . Should you require larger pictures then these can be emailed on request.



Left clean, tidy & rubbish free. No visible marks to walls and ceiling as all has been redecorated. The pictures illustrates. Should you require larger pictures then these can be emailed on request.





View of Sink

Sink: Left thoroughly cleaned and this is how it should be handed back on exit of your tenancy. Picture Illustrates. Should you require larger pictures then these can be emailed on request.



naea | propertymark

PROTECTED



View of Extractor Fan

Appliance: Left thoroughly cleaned and this is how it should be handed back on exit of your tenancy. Picture Illustrates. Should you require larger pictures then these can be emailed on request.



View of Hob

Appliance: Left thoroughly cleaned and this is how it should be handed back on exit of your tenancy. Picture Illustrates. Should you require larger pictures then these can be emailed on request.



View of Oven

Appliance: Left thoroughly cleaned and this is how it should be handed back on exit of your tenancy. Picture Illustrates. Should you require larger pictures then these can be emailed on request.







View of Fridge / Freezer

Appliance: Left thoroughly cleaned and this is how it should be handed back on exit of your tenancy. Picture Illustrates. Should you require larger pictures then these can be emailed on request.



Bedroom 1

12'11" x 13'8"

Replacement uPVC double glazed bay window to front with blinds, two fitted double wardrobe(s), double radiator, fitted carpet, double power point(s).

Left clean, tidy & rubbish free. No visible marks to walls and ceiling as all has been redecorated. The pictures illustrates. Should you require larger pictures then these can be emailed on request.



View of Bedroom 1

Left clean, tidy & rubbish free. No visible marks to walls and ceiling as all has been redecorated. The pictures illustrates. . Should you require larger pictures then these can be emailed on request.







Bedroom 1 Wardrobe

Left clean, tidy & rubbish free. No visible marks to walls and ceiling as all has been redecorated. The pictures illustrates. . Should you require larger pictures then these can be emailed on request.



Bedroom 1 Wardrobe

Left clean, tidy & rubbish free. No visible marks to walls and ceiling as all has been redecorated. The pictures illustrates. . Should you require larger pictures then these can be emailed on request.



Bedroom 2

 $12'6" \times 10'6"$

Replacement uPVC double glazed bay window to front with blinds, double radiator, fitted carpet, double power point(s).

Left clean, tidy & rubbish free. No visible marks to walls and ceiling as all has been redecorated. The pictures illustrates. Should you require larger pictures then these can be emailed on request.







View of Bedroom 2

Left clean, tidy & rubbish free. No visible marks to walls and ceiling as all has been redecorated. The pictures illustrates. . Should you require larger pictures then these can be emailed on request.



Bedroom 3

7'6" x 11'5"

Replacement uPVC double glazed window to side with blinds, single radiator, fitted carpet, telephone point, cable, double power point(s).

Left clean, tidy & rubbish free. No visible marks to walls and ceiling as all has been redecorated. The pictures illustrates. . Should you require larger pictures then these can be emailed on request.



Family Bathroom

Recently refitted with three piece suite comprising panelled bath with independent shower over with shower curtain, wash hand basin and low-level WC, full height ceramic tiling to all walls, heated towel rail, window to rear, ceramic tiled flooring.

Left clean, tidy & rubbish free. No visible marks to walls and ceiling as all has been redecorated. The pictures illustrates. . Should you require larger pictures then these can be emailed on request.







View of Family Bathroom

Left clean, tidy & rubbish free. No visible marks to walls and ceiling as all has been redecorated. The pictures illustrates. . Should you require larger pictures then these can be emailed on request.



Outside

Front Garden

Front boundary wall, laid to lawn, ample off road parking for 2/3 vehicles, access to the garage, access to the rear garden via garage.

Gardens, Frontage and Garage: Left neat and tidy as season presents. Should you require larger pictures then these can be emailed on request.



View Front Garden

Gardens, Frontage and Garage: Left neat and tidy as season presents. Should you require larger pictures then these can be emailed on request.



naea | propertymark

PROTECTED



Rear Garden

Enclosed by timber fencing, laid to lawn, side flower borders with mature shrubs plus graveled border. two patio area, one to the house and one to the rear of the garden. Access to the front via the garage.

Gardens, Frontage and Garage: Left neat and tidy as season presents. Should you require larger pictures then these can be emailed on request.



View of Rear Garden

Gardens, Frontage and Garage: Left neat and tidy as season presents. Should you require larger pictures then these can be emailed on request.



View of Rear Side Area

Gardens, Frontage and Garage: Left neat and tidy as season presents. Should you require larger pictures then these can be emailed on request.







View of Drive

Gardens, Frontage and Garage: Left neat and tidy as season presents. Should you require larger pictures then these can be emailed on request.



Single Garage

16'6" x 8'6"

Attached brick built single garage with rear personal door, power and light connected, double glazed window to rear, uPVC double glazed window to side, Up and over door, uPVC double glazed door.

Garage: The items in the garage, tools etc are left for the tenant to use, but need to be left on exiting the property. Left neat and tidy as season presents. Should you require larger pictures then these can be emailed on request.



Internal View of Single Garage

Garage: The items in the garage, tools etc are left for the tenant to use, but need to be left on exiting the property. Left neat and tidy as season presents. Should you require larger pictures then these can be emailed on request.



Property Condition Report

I/we have checked through the Inventory and Statement of Condition and have found them to be correct. All appliances are in working order and inventory items are in a good clean condition except where stated in the inventory & condition report.





Tenancy Date

Tenancy Start Date:

Tenants Signature.

Tenant(s) Signatures:

Tenants Printed Name.

Tenant(s) Name(s):

Additional Information & Keys

2 x Key witch fits the front, side and french doors.

1 x Garage front up and over door.

1 x Garage rear door.

Window keys are left in the windows.

Should the smoke alarm go off. To reset push the button on it and this will resent the alarm.

To activate the Alarm system.: 1963 - A - Yes. Then leave the property.

The Dis-Arm the Alarm: Enter 1963

Tenant(s) Application

Tenant(s) Applications:

Once you have found a suitable property to rent and all has been agreed, you will be required to complete our tenant(s) application form, which need to be completed individually and submitted with supporting documentation as follows. Photo ID: A valid Passport or ID Card (None UK or EU residences a residence card or valid Visa will be required)

Proof of Residence: A current utility bill.

Employment Details: Employment payment records (payslips or a P60).

Bank Statements: 6 Months bank statements (showing income & regular rental payments).

dg Property Consultants will not be unable to withdraw the property from the market until the completed application along with supporting documentation and the holding deposit has been received.

Right to Rent checks, Credit Checks/Searches and References:

These are all carried out by a professional referencing company, including previous landlord/letting agent references, current employment references and analysis of bank statements.

In the event of a Guarantor being required, the same reference procedure above will apply.

Once your application has been successfully completed, your tenancy will be agreed and set up, with the remainder of the deposit becoming immediately due. Followed by the payment of your first month's rent no more than 1 week prior to the start of your tenancy.

MISDESCRIPTIONS ACT - Lettings

MISDESCRIPTIONS ACT - dg property consultants for themselves and for the vendor of this property, whose agent they are, given notice that the particulars are set out as a general outline only for theguidance of intended purchasers and do not constitute or constitute part of an offer or contract. All descriptions, dimensions, reference to condition and necessary permissions for use and occupationand other details are given without responsibility, and any intending purchaser should not rely uponthem as statements or representations of fact but must satisfy themselves by inspection or otherwise as to their correctness. No person in the employment of dg property consultants, has any authority to make or any representation or warranty whatsoever in relation to this property.









